

PowerKleen
Quality Chemicals • Superior Service

Directions:

- Wet surface thoroughly with water before treating.
- Mix minimum of 50-50 with water and apply on surface no more than two (2) minutes in order for chemical to penetrate.
- DO NOT allow chemical to dry on surface.
- To help speed operation on heavily affected areas, agitate with towel, soft brush or sponge.
- Rinse thoroughly with pressure washer.

SUPER Fallout Remover

METAL FALLOUT PARTICLE REMOVER FOR PAINTED SURFACES

INDUSTRIAL STRENGTH FALLOUT REMOVER

- REMOVES METALLIC FALLOUT PARTICLES
EMBEDDED IN PAINTED SURFACES

CAUTION KEEP OUT OF REACH OF CHILDREN.

DO NOT TAKE INTERNALLY. HARMFUL IF SWALLOWED.

AVOID CONTACT WITH EYES AND SKIN.

1 Gal.

5 Gal.

55 Gal.

275 Gal.



TRANSPORT INFORMATION:

Proper Shipping Name - Compounds, Cleaning Liquid, N.O.S., (Contains Oxalic Acid)
DOT Hazard Class - 8 Packing Group - III
ID# - UN 1760

Inhalation: Remove affected person to fresh air; wash mouth & nasal passages with water repeatedly. If breathing difficulty persists, seek medical attention.

Skin: Remove contaminated clothing; wash affected area with soap and water; if irritation persists, seek medical attention. DO NOT attempt to neutralize with chemical agents. Launder contaminated clothing before reuse.

Eyes: Remove contact lenses. Flush eyes with clear running water for 15 minutes while holding eyelids open; get medical attention immediately.

Ingestion: Drink large quantities of water or milk; DO NOT induce vomiting; seek medical attention.

PowerKleen

Quality Chemicals • Superior Service

Power Kleen Corporation
To Reorder, Call: (813) 854-2648
FAX (813) 854-3133

In Case Of Chemical Emergency Contact
Chem-Tel 24 Hours (800) 255-3924

www.PowerKleen.com